



TECHNICAL DATA SHEET



BARIUM STEARATE

GRADE PM

SPECIFICATIONS

PROPERTIES	UNIT	LIMIT
Appearance	-	White powder
Ash (as BaO)	%wt.	28.0 – 30.0
Free Fatty Acid	%wt.	0.50 max.
Moisture	%wt.	2.0 max.
Melting point	oC	220 – 230
Water Soluble Salts	%wt.	1% Max.
Sieve Residue	200 Mesh	1% Max.